


# Electrical Safety Recall

Arlec Australia Pty Ltd is conducting a voluntary safety recall of its Swivel Plug extension leads limited to 3m, 5m, 7m and 10m – model SPL3, SPL5, SPL7 and SPL10 respectively. The affected extension leads were sold between 1st November 2009 and 16th January 2010 with Approval No. **SGSEA/090440** on the plug face. *No other Arlec extension leads are affected by this recall.*

The following markings are shown on the plug face.



## Defect Details & Potential Problem

There is a risk that the plug top cover may separate from the plug pins on applying excessive force thus exposing the live parts.

## Consumer Action

If the plug face has Approval No. **SGSEA/090440**, customers **must immediately stop using the identified extension leads.**

For a replacement or refund, or if you are unsure of the model number of the extension lead, please contact Arlec Customer Service for assistance on: Phone 03 9727 8860, Fax 1300 360 650 (toll free), [www.arlec.com.au](http://www.arlec.com.au)

**Arlec Australia Pty Ltd is committed to supplying quality products and is voluntarily recalling these extension leads in the interest of public safety.**

Arlec Australia Pty. Ltd. 272-274 Maroondah Hwy, Chirnside Park VIC 3116  
P.O.Box 181 Lilydale VIC 3140

**See: [www.recalls.gov.au](http://www.recalls.gov.au) for Australian Product Recall Information**