

SERVICE INSTRUCTION

Issued by:	Marius Andel	Ref. No.	SM-090505	Date:	5-May-09
Product(s):	Alimak Scando & Scando Super Construction Hoists, single or twin, TD or ID, DOL, FC or Hydraulic	Type:	10/20, 12/20, 20/20, 10/32, 20/30, 20/32, 20/37, 24/32, 24/37, 28/32, 28/37, 24/42, 28/42, 32/40		
Component(s):	Latch Locking Alimak Doors ("Gold Latch") # 9042 755 000				

SAFETY ALERT

In addition to the Safety Alert SM-090429 regarding the Alimak OEM's recommendation for Interlocking Device for Car Doors, this Safety Alert is issued by Alimak Hek Pty. Ltd. (Australia) at WorkSafe Victoria's request to notify about the Latch Locking for Alimak Doors, Part # 9042 755 000, as pictured in the photos below.



Latch Locking for Alimak Doors ("Gold Latch") Part # 9042 755 000

WorkSafe Victoria recommends the Latch Locking for Alimak Doors # 9042 755 000 should be fitted to all Alimak Scando products with vertical two-parts doors to ensure the doors are held closely together. This "Gold Latch" can not be use in-lieu/replace the "Cocky Catch" system, as mentioned by SM-090429.

Alimak Hek Pty. Ltd. - A.B.N. 80 005 538 947

Melbourne – Head Office
 2 Ausco Place
 DANDENONG SOUTH, VIC, 3175
 Ph: +61 (0) 3 8795 6789
 Fax: + 61 (0) 3 8795 6790

Sydney Office
 1-3 Ferndell Street
 SOUTH GRANVILLE, NSW, 2142
 Ph: +61 (0) 2 9790 9790
 Fax: +61 (0) 2 9632 0292

Internet: www.alimakhek.com.au

Brisbane Office
 Unit 10/210 Robinson Road
 GEEBUNG, QLD, 4034
 Ph: +61 (0) 7 3865 8188
 Fax: +61 (0) 7 3865 8488

SERVICE INSTRUCTION

All components are required to be verified to be in good functional and serviceable condition, within specified wear, tear and corrosion limits.



The installation, operation, functional checks and service are to be completed in accordance with Alimak Instructions for Spare Parts (Manual Part # 0461691), Installation (Manual Part # 9037093-1), Operation and Maintenance (Manual Part # 9023764-1) and Technical Description (Manual Part # 9023775-1).

Please feel free to contact Alimak Hek Pty. Ltd. if any further assistance is required.

Alimak Hek Pty. Ltd. - A.B.N. 80 005 538 947

Melbourne – Head Office
2 Ausco Place
DANDENONG SOUTH, VIC, 3175
Ph: +61 (0) 3 8795 6789
Fax: + 61 (0) 3 8795 6790

Sydney Office
1-3 Ferndell Street
SOUTH GRANVILLE, NSW, 2142
Ph: +61 (0) 2 9790 9790
Fax: +61 (0) 2 9632 0292

Internet: www.alimakhek.com.au

Brisbane Office
Unit 10/210 Robinson Road
GEEBUNG, QLD, 4034
Ph: +61 (0) 7 3865 8188
Fax: +61 (0) 7 3865 8488